

From: ["Wallingford, Jonni B." <wallingfordjb@cdmsmith.com>](mailto:WallingfordJonniB@cdmsmith.com)  
To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:SheldrakeSean@epa.gov)  
["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:ZhenDavis@epa.gov)  
CC: [younghs@cdmsmith.com](mailto:younghs@cdmsmith.com)  
["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:ScottCoffey@cdmsmith.com)  
Date: 7/25/2018 11:44:31 AM  
Subject: Subsurface Sediment Coring  
Attachments: [Snapchat-1480318796.jpg](#)  
[Snapchat-1766432920.jpg](#)

---

Good morning,

Included is a photo of the first subsurface core of the day, SC-S002 at RM 2.0 E, southwest the Port of Portland property line. The sample consists of silty sand with no observed odors or NAPL. The core was extracted with one attempt, yeilding a 103% recovery (due to expansion).

The 2nd photo shows the crew filling the pipe with ice to the top, ensuring the entire sediment core is iced. The PVC pipe is cut into sections that allow the crew to easily load the core. The bottoms are capped, minimizing ice melt.

Jonni

Get Outlook for Android<<https://aka.ms/ghei36>>